

 $\ensuremath{\mathbb{C}}$ Crown copyright and database rights 2020. Ordnance Survey 0100031673

٠	Turbines			
•	Met Mast			
	Site Boundary			
	Crane Pad and Temporary Laydown Area			
	Construction Compound			
	Substation			
	Borrow Pit Search Areas			
	Existing Track			
	Access Track Excavated			
	Access Track Floated			
/atercourse Crossing and Diversion				
•	Watercourse Crossing 1:50 K			
•	Watercourse Crossing 1:25 K or others			
	Gossa Water Scottish Water Drinking Water Supply Catchment			
	Surface Water Catchments			
	Scottish Water Raw Water Pipeline			
	SW Mains Water Distribution Pipeline			
	Watercourse 50 K			
	Watercourse 25 K and other			
	Drain or Gully Erosion			
	Man Made Drain			
	Water Quality Monitoring Point			
*	Peat Slide			
*	Tension Crack			
•	Spring			
*	Sinkhole			
0	0.5 km			
	KM			

Date:	Drawn by:	Checked by: LP	Version:
08/09/2021	JM		V1
			. –