



Borrow Pit A
Approximate extent marked with red dash. Steeply sloping ground and rock outcropping at the surface observed at this location



Borrow Pit B
Relatively steeply sloping ground observed at this location. Borrow pit may be accessed via a short stretch of existing farm track.



Borrow Pit D
Approximate location marked with red dash. Steeply sloping ground observed at this location



Borrow Pit B
Rocks at the ground surface observed.

Not to scale



Knockcronal Wind Farm
Environmental Impact Assessment Report
Appendix 3.2

Figure C.1

Photographs - Sheet 1