



Borrow Pit C
 Approximate location marked with red dash. Steeply sloping ground and rock outcropping at the surface observed at this location. Photograph taken from east side of borrow pit.



Borrow Pit E
 Relatively steeply sloping ground observed at this location. Borrow pit may be accessed via existing track. Some natural forestry regeneration



Borrow Pit C
 General photo at borrow pit location



Borrow Pit E
 Rocks at the ground surface observed.

Not to scale



Knockcronal Wind Farm
 Environmental Impact Assessment Report
 Appendix 3.2

Figure C.2

Photographs - Sheet 2